

Oil Field Environmental Incident Summary

Incident: 20141218093607 **Date/Time of Notice:** 12/18/2014 09:36

Responsible Party: Suspected Vandalism on CLR Well Location

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: ELVEIDA 1-33H

Field Name: SADLER

Well File #: 17275

Date Incident: 12/17/2014 **Time Incident:** 13:08

Facility ID Number:

County: DIVIDE

Twp: 161

Rng: 95

Sec: 33

Qtr:

Location Description:

Submitted By: Timothy Ilse

Received By:

Contact Person: Timothy Ilse
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	250	Barrels	250	Barrels	250	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 10/14/2016 **Clean Up Concluded:** 12/18/2014

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

Well site soil

Action Taken or Planned:

Standing oil was sucked up and returned to production tank, contaminated soil will be removed and clean material will be replaced.

Wastes Disposal Location: Oil returned to production tank; soil will be taken to Prairie Disposal.

Agencies Involved: Called Tom Delling @ 16:23 12/17/14

Updates

Date: 12/18/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to suspected vandalism, remained on location within the diking according to the report. NDIC retains oversight.